

SITE INVESTIGATION AND STATUS REPORT

ASBESTOS CONTAMINATION

JOHNS-MANVILLE FACILITY

WAUKEGAN, ILLINOIS

TDD# 5-8305-9

Roy F. Weston, Inc.
Spill Prevention & Emergency Response Division

In Association with Jacobs Engineering Group Inc., Tetra Tech, Inc. and ICF Incorporated

SITE INVESTIGATION AND STATUS REPORT

ASBESTOS CONTAMINATION

JOHNS-MANVILLE FACILITY

WAUKEGAN, ILLINOIS

TDD# 5-8305-9

Prepared by:

WESTON-SPER Technical Assistance Team

Kevin M. Pierard

10 June 1983

INTRODUCTION

On 18 May 1983 TAT was tasked to conduct a review of background information and an inspection on the Waukegan/Johns-Manville facility to determine if an emergency situation exists. TAT member Kevin Pierard scheduled the inspection for 24 May. It was rescheduled at the request of the company and completed on 1 June.

The Johns-Manville facility is located on approximately 300 acres in Waukegan, Illinois (Figure 1). Approximately 160 acres of that area are used for solid waste disposal and waste water treatment. Lake Michigan lies on the eastern edge of the company property.

The inspection revealed large areas of exposed waste (Figure 2) which Manville claims contain no friable asbestos. Of major concern are the solid waste dumping area, where a large amount of white fiberous material was exposed, the sludge spoil area and the area north of the center pump house trough.

Manville claims to abide by NESHAP regulations in regard to the asbestos disposal area. The regulations require that either there were no visible emissions or the waste was covered, within twenty-four hours, with at least six inches of compacted nonasbestos-containing material. The Manville facility began operations in the early 1920s. Few records are available which outline the types and quantities of waste disposed of on site. Although other types of wastes are mentioned, this report is concerned only with asbestos.

WASTE SURVEY BY JOHNS-MANVILLE

A waste survey was completed by Johns-Manville; the following section has been excerpted from this survey which was submitted by the company, in response to a USEPA inquiry on 7 April 1983.

"In April 1973, a survey was conducted of solid waste generated at the Waukegan facility. The survey considered wastes which previously had been generated but which for some reason had been discontinued and wastes which at that time were being disposed in the on-site disposal area. The results of the survey, which follow, recorded the estimated annual quantity of the waste as well as an estimate of the amount of asbestos contained in the waste.

APRIL 1973 SOLID WASTE SURVEY

Solid Wastes Previously Generated and Discontinued

Solid Wastes Disposed in April 1973

| Product | Annual Quantity | Estimated Percent Asbestos | <u>Status</u> |
|------------------------------|---------------------------------|----------------------------------|--|
| Auto & IND. Lining | 130,000 lbs. | 55% | Discontinued 4/30/83 |
| Barke Blocks | 315,000 lbs. | 65% | Discontinued 2/1/73 |
| No. 6401 Brake Blo | cks 16,000 lbs. | 39% | Discontinued 2/1/73 |
| 1257 Tan Brake Blo | cks 89,000 lbs. | 65% | Discontinued 2/1/73 |
| Friction Materials Sludge | 32,000 lbs. | 60% | Discontinued 5/1/73 |
| #60 Service Sheet | 838,000 lbs. | 80% | Cut gasket discontinued 12/15/72; reject sheet sold at discount to gasket cutters. |
| #61 Service Sheet | 200,000 lbs. | 80% | Cut gasket discontinued 12/15/72; reject sheet sold at discount to gasket cutters. |
| Disc Brakes | Inc. in F.M. Sludge | 60% | Discontinued 4/30/83 |
| Steel Back Clutch Facings | 10,000 lbs. | 60% | Discontinued 2/1/73 |
| Transite Pipe | 5,800,000 lbs. or 2,900 tons | 15% | Recycled |

Solid Wastes Disposed in April 1973

| Product | Annual Quantity | Estimated Percent Asbestos | <u>Status</u> |
|---|---|----------------------------------|---|
| Millboard Flexboard and Transitop | 25,000 lbs. 2,250,000 lbs | 80% 22% | No sheet material Trim, scrap and dust |
| Saturating Felt Roofing | 5,472,000 lbs or 2,736 tons | . 50% | No use found |
| Asphalt Roll Rfg. | 13,344,000 lb or 6,672 tons | s. 17% | 1/3 asbestos felt 2/3 organic felt |
| Transite Pipe | 8,748,000 lbs or 4,373 tons 572,000 lbs. or 286 tons w | dry 15% | Excess of recycle Wet end collector |

"In anticipation of filing the notification required by Section 3010 of RCRA, estimates of the quantities of hazardous waste, that prior to 18 August 1980 were identified under or listed pursuant to Section 3001 of RCRA, were made by Johns-Manville in August 1980:

| EPA No. | Generic Name | Trade Name or Use | Monthly Quantity |
|---------|--------------|-------------------|-----------------------------|
| F003 | Xylene | Paint thinner | 300 pounds |
| | Raw Asbestos | Asbestos | 750 pounds |
| D007 | Chromium | Chromic oxide | 14 pounds |
| B000 | Lead | 100B Lead | 4 pounds |
| U244 | Thiuram | Methyl Tuads | 1 pound plus 8 inner liners |

"It was also estimated at the time that the following quantities of hazardous waste were disposed in an encapsulated form, that is as the trim from or reject of a finished product:

WasteMonthly QuantityAsbestos14,190 poundsThiuram136 poundsLead298 poundsChromium3,077 pounds

"In addition, it was estimated that 17,410 pounds of waste asbestos per month was contained in the slurry going to the settling basins. However, with the shut down of the Waukegan facility's papermill and asbestos felt line in September 1981, it further was estimated that the amount of waste asbestos contained in the slurry would be reduced by 9,000 pounds per month.

"In the period which elapsed between filing the notification required by Section 3010 of RCRA and the filing of an application for a RCRA permit in November 1980, the Waukegan facility was successful in reducing the quantity of hazardous waste disposed. Various manufacturing processes were modified so that asbestos which formerly would have been disposed as waste was reused to manufacture products. The quantity of xylene which became waste was reduced by instituting a recovery procedure whereby xylene which was contaminated by paint was collected, was allowed to settle, and then was siphoned off. The xylene remaining after this procedure was a relatively small quantity which adhered to the paint particles and was disposed. In November 1980, it was estimated that the quantity of waste xylene would be eight gallons per year or approximately 65 pounds.

"Beginning in December 1980, monthly estimates have been made of the amounts of hazardous waste, as identified under or listed pursuant to Section 3001 of RCRA, and of raw asbestos disposed of in the on-site disposal area.

MONTHLY ESTIMATES OF HAZARDOUS WASTE AND RAW ASBESTOS (in pounds)

| Period | Raw Asbestos | D007** Chrome | D008** Lead | F003 Xylene | U244 Thiuram |
|-----------------------|-----------------|------------------|----------------|----------------|-----------------|
| 1980: Dec. | 54.9 | 22.5 | | | |
| <u>1981</u> : Jan. | 17.8 | | | | |
| Feb. | 83.6 | | | | |

** The quantities of chrome and lead estimated are not those derived as a result of performing the test for EP toxicity prescribed in USEPA's RCRA regulations, 40 C.F.R. § 261.24 (1982). Rather, these are gross quantities estimated to be contained in the waste disposed of on-site during the months indicated.

| Period | Raw Asbestos | DOO7 Chrome | D008 Lead | F003 Xylene | U244 Thiuram |
|--------|-----------------|----------------|--------------|----------------|-----------------|
| Mar. | 27.6 | 26.4 | | ~ = | |
| Apr. | 40.0 | 24.0 | | | |
| May | 30.9 | 26.4 | | | |
| Jun. | 36.9 | 4.4 | | | |
| Jul. | 36.2 | | 0.2 | ~- | 1.1 |
| Aug. | 33.2 | | 3.8 | ~- | |
| Sep. | 49.5 | | 0.8 | | 10.2 |
| Oct. | 137.9 | 1.6 | 1.0 | ~- | 61.0 |
| Nov. | 146.3 | 19.5 | 0.5 | | 61.9 |
| Dec. | 101.8 | 19.5 | 0.3 | •• | 43.7 |
| 1982 | | | | | |
| Jan. | 152.1 | | 1.0 | ~- | 80.0 |
| Feb. | 164.1 | | 1.0 | ~- | 80.0 |
| Mar. | 171.1 | | 1.0 | | 91.7 |
| Apr. | 87.2 | 27.2 | 1.0 | | 41.6 |
| May | 43.9 | 37.9 | 3.2 | | 19.8 |
| Jun. | 63.2 | | 1.0 | ~- | 19.0 |
| Jul. | 82.1 | | 1.0 | | 40.1 |
| Aug. | 124.8 | | 2.0 | ~- | 65.2 |
| Sep. | 85.0 | | 2.0 | ~- | 39.0 |
| Oct. | 72.6 | | 2.3 | ~- | 33.0 |
| Nov. | 23.4 | | 1.4 | | 4.6 |
| Dec. | 21.8 | | 1.1 | ~ | 3.5 |

| Period | Raw Asbestos | D007** Chrome | D008** <u>Lead</u> | F003 Xylene | U244 <u>Thiuram</u> |
|---------------|-----------------|------------------|-----------------------|----------------|------------------------|
| 1983: Jan. | 23.4 | | | | |
| Feb. | 23.1 | ** | | | |

monthly estimates given for raw asbestos are those non-encapsulated fiber disposed of by the facility. Such fiber is placed in plastic bags, sealed, and labeled and is placed in the on-site disposal area where it is covered, within twenty-four hours, inches of compacted, non-asbestos-containing least six material. In addition to this waste asbestos, other asbestos (in the asbestos fibers which have form of been encapsulated into a cementitious or rubber matrix, those which have been added to a slurry going to the settling basins, and those contained in sludges dredged from the settling basins and placed in designated sections of the on-site disposal area) is disposed at the facility in a manner which complies with that required by the NESHAP for asbestos.

"In reviewing these descriptions of the estimated volume and rate of asbestos and other hazardous substances disposed at the Waukegan facility's on-site disposal area, it must be noted that both the volume and type of waste disposed at the facility has changed over the years. This has occurred for a number of reasons. Because of changes in product lines, the asbestos fiber used in manufacturing at the Waukegan facility in 1981 was 41.6% of that used in 1974 and in 1982 was 7.7% of 1974. The amount of asbestos disposed also has been reduced because of the facility's success in reusing a large amount of asbestos which previously was disposed as waste. Finally, the depressed condition of the economy, in general, and of the building materials industry, in particular, has caused the Waukegan facility to reduce its production, and hence the amount of waste created and then disposed."

Any of the foregoing statements are strictly Johns-Manville information and have not been confirmed by TAT or the USEPA.

SAMPLING

On 28 April 1982, an airborne asbestos survey was conducted at the facility by Ecology and Environment, Inc. Field Investigation Team. 1 No attempt was made for compliance style sampling, samples were collected at upwind, midsite and downwind locations (Figure 3). Samples were collected over a 7.5 hour period on cellulose ester membrane filters and were drawn by Sierra/Andersen Virtual Impactors. Fibers with an aerodynamic size of 2.5 um to 15 um were collected on coarse filters, fibers less than 2.5 um were collected on fine filters. Results are as follows:

1Airborne asbestos survey - John Mansville, Waukegan, Illinois.
4-28-82
TDD# F5-8203-2-03

| Sample | Sample | Air Filtered | Calculated Chrysotile Fibers |
|--------|------------------|-------------------|------------------------------------|
| Number | Point | (m ³) | (fibers/CC ³) |
| A1613 | upwind (coarse) | .685 | 0.7 |
| A1614 | upwind (fine) | 6.15 | 0.02 |
| A1615 | midsite (coarse) | .752 | 12.0 |
| A1616 | midsite (fine) | 6.75 | 0.2 |
| A1617 | downwind (coarse | .752 | 21.0 |
| A1618 | downwind (fine) | 6.8 | 0.0 |

These results would indicate that significant amounts of chrysotile fibers were leaving the site, however, upon review by the Centers for Disease Control (CDC) some questions were raised as to the sampling and analytical techniques (letter dated 3 Decmeber 1982 from Superfund implementation group to Peter McCumiskey, EPA).

Specific comments from the CDC were:

"The type of sample collection was inappropriate for asbestos (any fibers). Using a Sierra/Anderson Virtual Impactor has no useful purpose in fiber collection, especially when fibers are going to be sized by electron microscopy. Total dust sample collection would have been the preferred method.

"Sample flow rates were too low for ambient air collection. Due to the sample device used, they were limited to 15.0 lpm.² With a total dust sample a much broader range of flow rates could have been used.

"Analysis by electron microscopy (EM) has not been standardized. Techniques such as type of filter, sample preparation methods, type of EM analysis, etc., vary depending on where the sample is collected (i.e., water, air) and the intended purpose of the collection (i.e., fiber concentration, fiber identification, fiber sizing). used in the study is one approach that is often used. However, there are some potential problems with the method. First, the cellulose filter used in collection needs to be ashed to remove organic material. It is then mixed with a dispersion solution and filtered through a nucleopore filter. During this process there is a potential for breaking fibers, thus increasing fiber counts/concentration; and losing some of the sample (fibers) during ashing and transfer of the material to the other filter type (nucleopore)."

² 1pm - liters per minute

Therefore, the CDC could not estimate the degree of health risk from the site with any certainty.

SITE HAZARDS

Due to the shape and small size of asbestos fibers, they may easily become airborne and remain so for long periods of time. There has been extensive documentation of the ability of airborne asbestos to cause cancer and lung damage through inhalation.

OSHA limits for employee asbestos exposure over an 8-hour period is 2 fibers, longer than 5 micrometers, per cubic centimeter of air. OSHA regulations set a ceiling concentration (one time exposure) limit at 10 fibers, longer than 5 micrometers, per cubic centimeter of air. These limits were initiated in 1976. The population within one kilometer is approximately 380, within five kilometers the population is 67,000.

RECOMMENDATIONS

We feel that the Manville facility may represent a threat to residents in the area; however, questionable air monitoring data and the lack of recent waste analysis make an accurate assessment impossible. It is therefore recommended that a waste sampling program be initiated at the site to determine if asbestos is present in the exposed refuse and sludge. If, in fact, asbestos is present in exposed material, that material should be watered down and covered with at least 6 inches, nonasbestos-containing material.

Air monitoring for asbestos during this operation should be done in a manner which is approved by NIOSH or the CDC.

FIGURE 1

ł


WESTERN 口 CONTOUR INTERVAL 10 FEET Zion Quad. 800 ILLINOIS 520

FIGURE

FIGURE 2

Ċ


1





All photos were taken on 1 June 1983 between 1030 and 1300,by Brad Benning (IEPA). Locations recorded by Kevin Pierard (TAT).

- Looking Northeast at asbestos waste dumping area.
- 2. Looking Northeast at South wall of the sludge spoil area.
- Looking East at the sludge spoil area.















- 4. Looking Northwest at area North of center pump house trough.
- Looking Northeast at mixing basin.
- 6. Looking Northeast from sludge spoil area berm at large settling basin.





- Looking Southwest at solid waste fill area.
- 8. Looking South at solid waste fill area.



€ SEIDIA







WESTON SPER

Region Date TDD#

5/25/83 5-8305-9

| A. | Incluent | Description |
|----|-----------------|--|
| | 1. | Location Johns-Manville 2. Date 5/25/83 |
| | | Greenwood Ave. |
| | | Waukegan, Il. 60087 |
| | 3. | Type: Spill / Fire / HW Site /x/ Other Asbestos Dis |
| | . 4. | Status Operating . |
| | 5. | Response Objectives Determine if Emergency action is needed |
| | 6. | Background Review: Complete xx/ Partial /_/ If partial, why? |
| - | 7- | Hazard Level: High // Moderate /XX/ Low // Unknown // Inhalation /X/ Ingestion // Contact // External // |
| | 8. | Site Plan/Sketch Attached Yes // No 🙀 |
| | 9. | Background Material attached Yes $\overline{//}$ No $\overline{/x/}$ |
| В. | <u>Material</u> | <u>Description</u> |
| | 1. | Type: Liquid / Solid kx/ Sludge / Vapor/Gas / |
| | 2. | Chemical Name/Class Asbestos (Amosite, Amphibole) |
| | _3. | Characteristics: Corrosive // Ignitable // Volatile // Toxic /x/ Reactive // Biological Agen |
| | 4. | Toxicity: TLV IDLH |
| | 5. | Special Hazards |
| | 6. | Acute Exposure Symptoms Shortness of breath of gradually increasing intensity and a dry cough. |

11/24/82

| C. Site De | escription | |
|------------|-------------------------------------|---------------------------------------|
| 1, | Size 300 acres | |
| 2. | Surrounding Population _ | approx, 400 within 1 mile |
| 3. | Buildings/Homes | |
| 4. | | Michigan 300 feet to the East |
| 5. | . Receiving Waters | e Michigan |
| 6. | . Weather 70 Sunny | |
| | • | |
| | | |
| 8 | • | opened in early 1900's |
| ٠ | · | • |
| | el Protection | · · · · · · · · · · · · · · · · · · · |
| 1 | , | e clothing: A / B / C /x/ D / J |
| 2 | . If not B, why? Contamina | nt did warrant Level B |
| 3 | . Site Instrument Readings | • |
| | % 02 | % LEL |
| | Radioactivity OVA | HNU Other |
| 4 | Up or Down graded to: A Why | or downgraded: Yes // No /x/ |
| | | |
| 5 | . Respirator Protective Equ | |
| | SCBA Gas Mask | Canister Type |
| | Gas Mask Ultra Twin Dust Mask | Cartridge Type GMD-H Combination |
| 6 | . Protective Clothing: | |
| | Boot Covers | Nitril gloves |
| | "Steel toe boots- | Hard hat |
| | Tyvek suit | Ultra twin |
| | | · · · · · · · · · · · · · · · · · · · |

| • | 7. | Field Monitoring | g Equipmen | t and Mar | terials: | | |
|----------|----------|--------------------------------------|--------------------------|------------------|---|-------------------------------|--------------|
| | | None | | | | | |
| - | | | | | | | |
| | | | | | | | |
| - | | | | | | | |
| | | | | | 7 | | |
| E. | Decontam | Ination Procedur | es | | | | |
| | 1. | Attach sketch s Support Zone an | howing Exc d numerica | lusion Zo | on e, C ontaminati lled Decontamina | on Reduction Zetion Stations. | one, |
| | 2. | For each decont on an attachmen | | station | note procedure a | nd materials n | eeded |
| F. | General | Information_ | | | | | |
| \smile | 1. | Team members | | | | • . | |
| | | Kevin Piera | ard | | • <u></u> | | |
| | | | | | · · · · · · · · · · · · · · · · · · · | | |
| | 2. | Site Safety Coo | rdinator . | Kevin | Pierard | | |
| G. | Emergenc | y Information | | | | | |
| | 1. | Have nearby peo If yes ever how | ple been e large an | vacuated area | : Yes /_/ | No /x/ | |
| <u> </u> | 2. | First Aid Instr | | remove di | sabled person to | uncontaminated | area_ |
| | 3. | Sources of help | | | | | |
| | | \ | 1 | Name | Tow n | Phone | Notii Yes |
| | | Fire | Waukega | an | | 689-7503 | |
| | | Police Ambulance | - | | Waukegan | 689-7550 | No NO |
| | | Hos pital | St, Teres | 5 | Waukegan | 249~3500 | No |
| • | | Poison info Airport | ormat ion | | - | | |
| | | Heliport Site Telep Nearest Te | | Johns- Ma | nville Waukegan | 623~2900 | |

| | 4. Emergency Telephone Numbers | · |
|----------|---|---|
| | WESTON NPO 215- P. B. Lederman - NPM 201- S. M. Gertz - HSO 215- Medical Emergency 513- EPA - ERT Emergency 201- Chemtrec 800- Central Disease Control 404- | 524-1925 or 1926 431-0797 or 0798 or 692-3030 665-0359 (Home) 667-5461 (Home) 421-3063 (National Service) -321-6660 424-9300 329-3311 (day) 404-329-3644 (night) 845-7633 (Regional Service) |
| (For HSC | Date Appr Date 50 Use Only) | oved by Justine 15/25/83 |
| 1 | Reviewed and Comments | |
| ! | Action Required? Yes // No // | If yes, what action |
| 1 | Followup carried out? Date | |
| 1 | | |
| | S. O. Signat | ure Date |